KENNY C. GUINN Governor

MEMBERS
Michael Zech, Chairman
Douglas W. Carson
Margaret Cavin
David W. Clark
Jerry Higgins
Dennis K. Johnson
Randy Schaefer

State Of Nevada



STATE CONTRACTORS' BOARD

Reply To:

RENO 9670 Gateway Drive, Suite 100 Reno, Nevada 89511 (775) 688-1141 Fax (775) 688-1271 Investigations: (775) 688-1150

www.nscb.state.nv.us

LAS VEGAS

2310 Corporate Circle, Suite 200 Henderson, Nevada 89074 (702) 486-1100 Fax (702) 486-1190 Investigations: (702) 486-1110

February 22, 2002

Lorne Malkiewich, Esq. Director Legislative Counsel Bureau 401 South Carson Street Carson City, NV 89701-4747

Dear Mr. Malkiewich:

Enclosed is a copy of the quarterly report ending December 31, 2001 outlining disciplinary actions taken by the Nevada State Contractors Board.

The report is submitted in compliance with NRS 622.010. I apologize for the delay in providing the report to you.

If you need further information, please feel free to call me in Henderson at (702) 486-1111 or in Reno at (775) 850-7878.

Sincerely,

Margi A. Grein
Executive Officer

Enclosure

Hearing Date Respondent	<u>Lic.No.</u> <u>Violations</u>	Violation	<u>No</u> <u>Violation</u>		Fine Assessed	Investigative <u>Costs</u>	Revoke	Susp.
10/9/01 Supply One, Inc.	47467 624.3012(2) 624.302(5) 624.3013(3) 624.3013(5)			Board accepted Surrender of License Number 47467				
10/9/01 Lakemont Homes	42420 624.3017(1) 624.3013(5)		X X	Dismissed all charges				
10/9/01 B K Construction	43775 624.3017(1) 624.3013(5) 624.3011(1)(a) 624.3013(5) 624.3016(6)	X X	X X X	6 month Ltr of Reprimand				
10/9/01 K G Walters	17382 624.3017(1) 17383 624.3013(5) 42498 624.3011(1)(b)(1)	X X X		Dismissed all charges				
10/9/01 Blades Construction	23397 624.3017 (1)x2 624.3013 (5)x2 624.3011 (1)			Staff Update/				
10/9/01 Carson City Roofing DEFAULT	42990 624.3012(2) 624.302(5) 624.301(5) 624.3013(3) 624.3013(5) 624.3013(4)	X X X X X		Guilty as charged		\$1,348.00	1	

Hearing Date Respondent	Lic.No. Violatio			Investigative Fine Assessed Costs	Revoke Susp.
10/9/01 T L C Builders	34059 624.3015(1) 624.3013(5) 624.302(5)		Continued to LV Hearing		
40/00/04 F			Found in violation of all charges. License REVOKED . Inv. costs of \$1,865 to be paid prior to		
10/23/01 Freedom Plumbing			relicensure.	\$1,865.00	1
	624.3012(2) 624.3013(5)				
10/23/01 HCl Hinnewinkel	44681 624.3012(2) 624.3013(3) 624.3013(5)	X	Found in violation of all charges. License REVOKED . Inv. costs of \$927 to be paid prior to relicensure.	\$927.00	1
High Bluff 10/23/01 Construction	37446 624.3012(2) 624.302(5) 624.3013(3) 624.3013(5)	X X X	Found in violation of all charges. License REVOKED . Inv. costs of \$1,055 to be paid prior to relicensure.	\$1,055.00	1
Rotating Tech. D/b/a/ Las Vegas 10/23/01 Demolition	32796 624.3012(2) 624.302(5) 624.3013(3) 624.3013(4)		Continued to December 18, 2001		

<u>Hearing</u> <u>Date Respondent</u>	Lic.No.	<u>Violations</u>	<u>Violation</u>	<u>No</u> <u>Violation</u>	Disposition or Resolution	<u>I</u> <u>Fine Assessed</u>	nvestigative <u>Costs</u>	Revoke	Susp.
10/23/01 Allied Underground	28255 & 28237	624.3012(2)x2 624.3013(3) 624.302(5)	× × ×		Found in violation of all charges. License REVOKED . Inv. costs of \$1,566 to be paid prior to relicensure.		\$1,566.00	2	
Tri Star Theme 10/23/01 Builders	47219 & 40861	624.3012(2) 624.3013(3) 624.3013(4) 624.3013(5)x2	X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$1,665 to be paid prior to relicensure.		\$1,665.00	2	
10/23/01 Raincross Develop.	35962	624.3012(2) 624.3013(3) 624.3013(4) 624.3013(5)x2	X X X		See Tri-Star Theme Builders			1	
Sunset Construction d/b/a Primier 10/23/01 Construction		624.3012(2) 624.3013(3) 624.3013(5) 624.3018(2)	X X X		Found in violation of all charges. License REVOKED . Respondent shall be refunded \$500 renewal and cash bond			1	
10/23/01 Keith Maris Drywall	28526	624.3012(2) 624.3011(1)(b)(2) 624.3012(5)(6) 624.3013(3)			Continued for 30 days to provide current f/s. If f/s not provided by 11/20/01 license will be suspended.				

Hearing <u>Date</u>	Respondent	Lic.No.	<u>Violations</u>	<u>Violation</u>	<u>No</u> <u>Violation</u>	Disposition or Resolution	Fine Assessed	Investigative Costs	Revoke	Susp.
10/23/01	Empire Roofing	33573	624.3012(2) 624.302(5) 624.3013(3)			Ltr of Reprimand for 1 Yr. Prove that LV Roofing Supply is paid. Provide financial stmt.				
10/23/01 \	Walchop, Inc.	17738 & 17734	624.3012(2) 624.302(5) 624.3013(3)	X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$1,176 to be paid prior to relicensure.		\$1,176.00	2	
10/23/01	Howell Development	46879A	624.3012(2) 624.302(5) 624.3013(3) 624.3013(4)	X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$1,072 to be paid prior to relicensure.		\$1,072.00	1	
10/23/01	Cutting Construction	15695				Rescheduled for 11/20/01				
	Terra Landscape & Concrete Construction	49047	624.3016(1) 624.3013(3) 624.3013(5) 624.3015(1)	X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$1,671 to be paid prior to relicensure.		\$1,671.00	1	
			624.3011(1)(b)(1)	x						

Hearing <u>Date</u>	Respondent	<u>Lic.No.</u>	<u>Violations</u>	<u>Violation</u>	<u>No</u> Violation	Disposition or Resolution Found in violation of all charges. License REVOKED. Inv. costs of \$1,150 to be paid prior to	Ir Fine Assessed	nvestigative <u>Costs</u>	Revoke	Susp.
10/23/01	Euro Electric	45162 & 50705	624.3012(2) 624.302(5) 624.3013(3) 624.3013(4)	X X X		relicensure.		\$1,150.00	2	
11/7/01	No Hearings in Reno									
11/20/01	Keith Maris Paint & Drywall	28526	6 624.3012(2) 624.3011(1)(b)(2) 624.302(5)&(6)	X X X		Found in violation of all charges. Fined \$1,000 per violation. One year letter of reprimand and inv. costs of \$1,456.00 to be paid within 90 days.	\$1,000 \$1,000 \$1,000	\$1,456.00		
	Vinzants Plastering dba JW Tile and John W. Vinzants					Found in violation of all charges. Fined \$2,000. Permanent letter of reprimand and inv. costs of \$1,754.00 to be paid within 90 days or license authomatically				
11/20/01	dba Johns Decking	32918 &32919	624.3017(1) 624.3017(1) 624.6958(2)(d)(f)(h) (l)(l)(m)(n)(0) NAC	×××		suspended.	\$2,000	\$1,754.00		
			624.6964(1),(5) NAC 624.6966(2) NAC 624.640(5) NRS 624.600	X X X						

Hearing Date	<u>Respondent</u>	Lic.No.	<u>Violations</u>	<u>Violation</u>	<u>No</u> <u>Violation</u>	Found in violation of all	<u>Fine Assessed</u>	nvestigative <u>Costs</u>	Revoke	Susp.
11/20/01	Laskowski Construction	4887	2 624.3017(1) 624.3013(5)	X X		charges.One year letter of reprimand and inv. costs of \$2,869.00 to be paid within 60 days or license authomatically suspended.		\$2,869.00		
11/20/01	Pahrump Concrete	26957, 31120, 31121, 35508 and 36676	624.3017(1) 624.3013(5)		X X	Charges dismissed.				
11/20/01	Granite Inc., dba Granite Options Etc.	41889	9 624.3017(1) 624.3013(5) 624.3015(1) 624.3014(1) NAC 624.640(5)	X X X X		Found in violation of all charges.Inv. costs of \$1,486.00 to be paid prior to consideration of relicensure.		\$1,486.00		
11/20/01	Coopcon, Inc. dba Paradise Carpets	41549	9 624.3011(1)(b)(2) 624.302(5) 624.3013(3)	X X X		Found in violation of all charges. Suspension of lic. For 1 yearto allow resp. to take care of labor comm. Issues. Resp. needs to come before the Board to reinstate lic If not done within 1 year lic. will be revoked.				1
11/20/01	Empire Roofing	33573	3 624.3012(2) 624.302(5) 624.3013(3)			Continued to 12/18/01				

Hearing <u>Date</u>	Respondent	Lic.No.	<u>Violations</u>	<u>Violation</u>	<u>No</u> <u>Violation</u>	Disposition or Resolution	Fine Assessed	Investigative <u>Costs</u>	Revoke	Susp.
11/20/01	Edward Grady Webb dba E. W. Development	3878	4 624.3017(1) 624.3013(5)			Continued to 12/18/01				
11/20/01	Robt. L. Lockwood dba Arwoods Kitchen Refacing	3149	9 624.3017(1) 624.3013(5) 624.3011(1)(a) 624.3013(5)			Continued to 01/23/02				
11/20/01	ADA Compliance Corporation	48704, 48702, 48703	624.301(2) 624.301(4) 624.3014(1) 624.3013(5)			Continued to 01/23/01				
11/20/01	Chlorine Free Swimming, Inc.	4431	9 624.3017(1) 624.3013(5) 624.600(1) 624.720(2) 624.3014(1) 624.301(5) 624.640(5)	X X X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$1,179 and full restitution to be paid prior to consideration of relicensure.		\$1,179.00	1	

Hearing Date Respondent	Lic.No.	<u>Violations</u>	Violation	<u>No</u> Violation	Disposition or Resolution	Fine Assessed	Investigative Costs	Revoke	Susp.
11/20/01 Able Iron		624.3017(1) 624.3013(5) 624.3013(3) 624.3013(4) 624.640(3)	X X X X	youton	Found in violation of all charges. License REVOKED. Inv. costs of \$1,023 and full restitution to be paid prior to consideration of relicensure.		\$1,023.00	1	Suchi
Master Plumbing and Mechanical and 11/20/01 LG&G Company	13954 and 13920	624.3012(2) 624.3013(3) 624.3013(5) 624.3018(2)	X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$1,258and full restitution to be paid prior to consideration of relicensure.		\$1,258.00	2	
Gialdos Carpentry 11/20/01 Shop	45795	624.301(1) 674.302(5) 624.3013(5) 624.3014(1) 624.3013(4) 624.640(3)	X X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$1,133 and full restitution to be paid prior to consideration of relicensure.		\$1,133.00	1	
11/20/01 G & M Concrete Inc.	45120	624.3017(1)	×		Found in violation of all charges. License REVOKED . Inv. costs of \$1,236 and full restitution to be paid prior to consideration of relicensure.		\$1,236.00	1	

Hearing Date	Respondent	<u>Lic.No.</u>	<u>Violations</u> 624.3013(5) 624.302(5) 624.3018(2)	Violation X X X	<u>No</u> <u>Violation</u>	Disposition or Resolution	Fine Assessed	nvestigative <u>Costs</u>	Revoke	Susp.
11/20/01 -	Gary Gene Kellershon dba Gary G. Kellershon Enterprises		624.3017(1) 624.302(5) 624.3013(5) 624.3013(4) NAC 624.640(3) & (5)	X X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$2,566 and full restitution to be paid prior to consideration of relicensure.		\$2,566.00	1	
11/20/01	Camilles Warren Lindell, Jr. dba Tri State Restoration	43904	624.3015(2) 624.302(5) 624.3013(5) 624.3013(3) 624.3013(4) 624.3015(1)	X X X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$1,008 and full restitution to be paid prior to consideration of relicensure.		\$1,008.00	1	
11/20/01	Mattson Builders, Inc. dba Nevada Spray Foam and Mattson Builders Inc.	45132, 40389 and 33180A	624.3017(1) 624.301(5) 624.302(5) 624.3013(5)	X X X		Found in violation of all charges. License REVOKED . Inv. costs of \$1,016 and full restitution to be paid prior to consideration of relicensure.		\$1,016.00		

Hearing Date]_ Respondent	Lic.No.	Violations NAC 624.640(3) &	<u>Violation</u>	<u>No</u> <u>Violation</u>	Disposition or Resolution	Fine Assessed	Investigative Costs	Revoke	Susp.
			(5) 624.3013(4)	×						
12/4/	01 F J D Enterprises		624.3017(1) 624.3013(5) 624.3013(5) 624.3018			Reimburse homeowner \$725.00 6 month letter of reprimand				
12/4/	01 Arneson Develop	24166	624.3017(1) 624.3013(5) 624.3015(1)			Make temporary repairs (3 weeks) Continue to LV Hearing 12-18 Permanent repairs in 6 months				
12/4/	01 Reno Constr	41932	624.3012(2) 624.3013(3) 624.3013(5)			Continued to January 8, 2002				
	L J Constr/L J									
12/4/	01 Fencing	41539/43414	624.301(2)	Х				\$2,041.00	2	
						Found in violation of all charges, but dismissed 4th cause. Licenses REVOKED . Inv. costs of \$2041 and full restitution to be paid prior				
			624.3013(5)	X		to consideration of relicensure.				
			624.3015(2)	X						
			624.3015(1)		X					
			624.3018(2)	X						
			624.3013(5) 624.3013(5)	X						

Hearing Date Respondent	<u>Lic.No.</u> <u>Violations</u>	<u>Violation</u>	<u>No</u> <u>Violation</u>	<u>Disposition or Resolution</u> Found in violation of all charges.	Fine Assessed	Investigative Costs	Revoke	Susp.
12/4/01 Hansen Electric Default	31518 624.3013(3) 624.302(5) 624.3013(5)	X X X		License REVOKED . Inv. costs of \$1938 and full restitution to be paid prior to consideration of relicensure.		\$1,938.00	1	
12/4/01 T L C Builders	34059 624.3015(1) 624.3013(5) 624.302(5)	X X	X	1 year letter of reprimand				
12/4/01 Blades Constr	23397 624.3017(1)X2 624.3013(5)X2 624.3013(5)			Found in violation of all charges. \$3000.00 per violation x5=\$15,000.00 License REVOKED . Inv. costs of \$9416 and full restitution to be paid prior to consideration of relicensure.	\$15,000.00	\$9,416.00	1	
12/18/01 Cutting Construction	15695 624.3017(1) 624.3013(5) 624.3015(3) 624.3013(1) 624.3014(2) 624.3013(3) 624.3015(1) 624.3013(5)			Continued to Jan. 23 or 24, 2002				
12/18/01 Cambridge Dev.	47488 624.3017(1) 624.3013(5)			Continued to Jan. 23 or 24, 2002				

				<u>No</u>			Investigative		
Respondent	Lic.No.		<u>Violation</u>	<u>Violation</u>	Disposition or Resolution	Fine Assessed	Costs	Revoke	Susp.
		624.3013(3) 624.3015(2)							
					Found in violation of all charges. 1 Year Letter of Reprimand. Provide proof of LV Roofing Supply being paid within 30 days; revise F/S to show receivables and take off "draft" or license will be				
Empire Roofing	33573	3 624.3012(2) 624.302(5) 624.3013(3)	X X X		suspended.				
Rotating Technology									
dba LV Demolition	32796	6 624.3012(2) 624.302(5) 624.3013(3) 624.3013(4)			Continued to Feb. 20, 2002				
Danny Henderson	14879, 23891 &								
Enterprises	29904	624.3017(1) 624.3013(5) 624.301(5) 624.3013(5) 624.3013(3)			Continued to Jan. 23 or 24 2002		\$2,741.00		all licenses suspended for 1 year
Flex Electric dba Thunderbird Elec.	36675	6 624.3012(2) 624.302(5) 624.3013(3)			Place on inactive status for max. of 24 mos to try & establish financial resp. If not done w/in 24 mos. License to be revoked.				
	Rotating Technology dba LV Demolition Danny Henderson Enterprises Flex Electric dba	Empire Roofing 33573 Rotating Technology dba LV Demolition 32796 Danny Henderson 14879, 23891 & 29904 Flex Electric dba	Empire Roofing 33573 624.3012(2) 624.302(5) 624.3013(3) Rotating Technology dba LV Demolition 32796 624.3012(2) 624.3013(3) 624.3013(3) 624.3013(4) Danny Henderson Enterprises 29904 4879, 23891 & Enterprises 29904 624.3017(1) 624.3013(5) 624.301(5) 624.301(5) 624.3013(3) Flex Electric dba Thunderbird Elec. 36675 624.3012(2) 624.302(5)	Empire Roofing 33573 624.3012(2) X 624.302(5) X 624.3013(3) X Rotating Technology dba LV Demolition 32796 624.3012(2) 624.3013(3) 624.3013(4) Danny Henderson 14879, 23891 & Enterprises 29904 624.3013(5) 624.3	Respondent Lic.No. Violations Violation Violation 624.3013(3) 624.3015(2) 624.3015(2) X 624.3012(2) 624.302(5) 624.3013(3) X Rotating Technology dba LV Demolition 32796 624.3012(2) 624.3013(3) 624.3013(3) 624.3013(4) 624.3012(2) 624.3013(5) 624.3015(5) 624.3015(5) 624.3013(3) Danny Henderson Enterprises 14879, 23891 & 29904 624.3017(1) 624.3013(5) 624.3013(5) 624.3013(3) Flex Electric dba Thunderbird Elec. 36675 624.3012(2) 624.302(5)	Respondent	Respondent	Respondent	Respondent Lic.No. Violations Violation Disposition or Resolution Eine Assessed Costs Revoke

Hearing Date Respondent Green Valley	Lic.No.	<u>Violations</u>	Violation	<u>No</u> <u>Violation</u>	Disposition or Resolution	Fine Assessed	Investigative <u>Costs</u>	<u>Revoke</u>	Susp.
12/18/01 Builders	3987	7 624.3012(2) 624.302(5) 624.3013(5)			Continued to Jan. 23 or 24, 2002				
12/18/01 Smooth Air	3626	5 624.3017(1) 624.302(5) 624.3013(5) 624.301(1) 624.3013(3) 624.3015(5) 624.3013(5)			Continued to Jan. 23 or 24, 2002				
Complete Const. & 12/18/01 Remodeling	39988, 39989 & 39990	624.3015(1) 624.3011(1)(b)(1) 624.3015(1) 624.302(5) 624.301(5) 624.3013(5) 624.3013(4) 624.3018(2)	X X		Remove Monument Const. From complaint. Complete Const. Found in violation of 624.3011(1)(b)(1) and 624.302(5). 2 year letter of reprimand. Full restitution to all damaged partied and investigative fees of \$1,709 to be paid prior to reactivation of license.		\$1,709.00		
12/18/01 Panda Refrigeration	26472	624.3012(2) 624.3013(3) 624.3013(4)			Continued to May 21, 2002				

Hearing Date	Respondent	Lic.No.	<u>Violations</u>	<u>Violation</u>	<u>No</u> Violation	Disposition or Resolution	Fine Assessed	Investigative Costs	Revoke	Susp.
12/18/01	Desert Roofing	47	976 624.3017(1) 624.3013(5) 624.301(5) 624.3011(1)(b)(1) 624.3013(5)			Staff Update at 30 & 60 days. Continued to March 19, 2002.				
12/18/01	EW Development	38	784 624.3017(1) 624.3013(5)			Continue to Jan. 24 or 24, 2002				
						Found in violation of all charges. License REVOKED . Full restitution to all damaged parties and recovery of investigative fees & legal costs in the amount of				
	RBM Concrete					\$1,392 to be paid prior to				
12/18/01	Construction	40337A	624.3012(2) 624.302(5) 624.3013(3) 624.3013(5) 624.3013(5)	X X X X		consideration of relicensure.		\$1,392.00	1	
12/18/01	RJ Development	40	727 624.3017(1) 624.3013(5) 624.3013(5) 624.3013(3)			Continued to February 20, 2002.				
12/18/01	The Bottom Line	25	606 624.301(1) 624.3011(1)(b)(1) 624.3013(5) 624.3013(5) 624.3015(1) 624.3011(1)(a)			Continue to February 20, 2002				
2nd Quarter	r Totals						\$20,000.00	\$47,975.00	32	1